

Smith & Nephew Knee Implant Recall

- Oxinium Genesis II
- Profix II Knee Implants

News reports revealed problems with 2 models of Smith & Nephew cementless artificial knees that led to a recall in September, 2003. The two models, the Oxinium Genesis 2 and the Profix 2 were used in implant operations between June of 2002 and March of 2003. These models failed to bond properly and became loose. As a result, many patients required additional corrective surgery, suffered infections and experienced further joint and muscle damage, often leading to painful rehabilitation.

KNEE IMPLANT RECALLS

- SMITH & NEPHEW OXINIUM CEMENTLESS KNEE
- STRYKER OSTEONICS
- HOWMEDICA DURACON KNEE
- PREMATURE POLYETHYLENE INSERT FAILURE